

APPLICATION OF ACOUSTIC WAVES FOR ASSESSMENT OF EXCAVATION DAMAGED ZONE FOR UNDERGROUND CONSTRUCTION IN ROCK MASS

Hoang Dinh Phuc¹, Chu Viet Thuc²

¹ Hanoi University of Mining and Geology, Vietnam

² Electric power University, Vietnam

Corresponding author' Email: hoangphucmdc@gmail.com

Abstract: It is inevitable that excavation at deep underground powerhouse in high in-situ stresses induced damages to the surrounding rocks. As a result, reasonable determination of the excavation damage zone (EDZ) is critical to the design, construction and safe operation of the underground powerhouse. This study divides EDZ into excavation highly damaged zone (EHDZ), excavation slightly damaged zone (ESDZ) and undamaged zone (UDZ) so as to better capture the evolving characteristics of the surrounding rocks at deep underground powerhouse in high in-situ ground stresses. With the utilization of acoustic detection, this study introduces the damage factor D to quantitatively distinguish the EDZ. Borehole camera is also employed to observe the characteristics of fissure development within the surrounding rocks. The observed damage characteristics of the surrounding rocks are then compared against the acoustic detection results, showing favorable agreement. Based on the actual engineering practice, this study puts forward the discriminating standard for the EDZ at deep underground powerhouse in high in-situ stresses during construction. Hopefully, this study could provide some basis for the evaluation of degree of damage of the surrounding rocks as well as the informational design and construction at underground powerhouse with similar conditions.

Keywords: rock mechanics; EDZ; acoustic detection; borehole camera imaging; damage factor.

1. Introduction

With the rapid development of China's economy, the demand on energy is on the rise. Since the implementation of policies regards development of the west regions, more and large hydropower stations have cropped up across China, especially in the valley regions of western China. Construction of the large hydropower stations in valley regions gives rise to a series of problems, such as deep burial depth and long span of the underground powerhouse. In addition, increasingly serious problems such as the damage of surrounding rocks during excavation have also captured more and more attention from the engineers and scholars in China and abroad.

As a complex geologic body, rock mass is usually subject to complicated stresses. It is known to us all that in situ rock mass are subject to three-dimensional stresses. The excavation of underground powerhouse disturbs the stress

balance and alters the stress regime. Also, the excavation of underground powerhouse affects the mechanical properties and water-physical properties of the surrounding rocks. The effect is mainly manifested in aspects such as a great amount of fissures generated within the rock mass, rapid fissure development and fissure coalescence. As a result, permeability coefficient of the rock mass is increased, creating channels for water intrusion. Therefore, it is of great engineering significance and theoretical value to study the EDZ at deep underground openings in high in-situ ground stresses during construction and its implications for support parameters optimization, safe construction and evaluation of engineering stability and safety.

A significant number of studies at China and abroad have been carried out regarding EDZ partition and zonal support during excavation of underground openings. With consideration of the